

Arduino

R2

5er5

IC

HC 7-

Rotation

Stepper 2

Endstop

5795

5795

Stepper 1

R1

GND

AREF

13

12

11

10

9

8

7

6

5

4

3

2

1

TX0

RX0

5V In

J12

J11

Jamper

5

Magnet

5795

R1

Magnet

R1

TX0

RX0